

BEFORE THE ARIZONA CORPORATIO

27

28

COMMISSIONERS BOB STUMP - Chairman

SUSAN BITTER SMITH

GARY PIERCE BRENDA BURNS BOB BURNS

Arizona Corporation Commission

DOCKETED

DEC 1 6 2013

DOCKETED BY	and the second section of the section of
and the second s	MR

IN THE MATTER OF THE)	DOCKET NO. W-03514A-13-0365
APPLICATION OF PAYSON)	
WATER CO., INC. FOR APPROVAL)	ADMINISTRATIVE CLOSURE
OF A CROSS-CONNECTION OR)	
BACKFLOW TARIFF.)	NUMBER 74218

10 A request to close the above-referenced matter was filed on November 29, 2013, by Renee de la Fuente, Administrative Assistant III for the Utilities Division. By memo, this tariff became effective by operation of law on November 24, 2013.

An Administrative Closure Number has been assigned to this matter which officially closes the 13 docket. This is not a signed order of the Commission and is for record keeping purposes only.

If you have any questions regarding this matter, please contact me at (602) 542-3477.

Administrative Closure Number issued On this 16th day of December 2013.

Docket Administrator

Docket Control

1 2 A copy of the foregoing Administrative Closure was mailed to the following by the Docket Control Center on December 16, 2013. Jason Williamson Payson Water Co., Inc. 5 7581 E. Academy Blvd. – 229 Denver, CO 80230 Steven M. Olea, Director Utilities Division 8 | 1200 West Washington Phoenix, Arizona 85007 Janice Alward, Chief Legal Counsel Legal Division 11 1200 West Washington Phoenix, Arizona 85007 12 Lyn Farmer - A.C.C. Chief Hearing Officer 13 Hearing Division 1200 West Washington Phoenix, Arizona 85007 15 16 17 18 19 20 21 22 23 24 25 26 27

28

CROSS-CONNECTION OR BACKFLOW TARIFF

PURPOSE:

The purpose of this tariff is to protect Payson Water Co., Inc. ("Company") water from the possibility of contamination caused by the backflow of contaminants that may be present on the customer's premises by requiring the installation and periodic testing of backflow-prevention assemblies pursuant to the provisions of the Arizona Administrative Code ("A.A.C.") R14-2-405.B.6 and A.A.C. R18-4-215.

REQUIREMENTS:

In compliance with the Rules of the Arizona Corporation Commission ("Commission") and the Arizona Department of Environmental Quality ("ADEQ"), specifically A.A.C. R14-2-405.B.6 and A.A.C. R18-4-215 relating to backflow prevention:

- 1. The Company may require a customer to pay for and to have installed a backflow-prevention assembly if A.A.C. R18-4-215.B or C applies.
- 2. A backflow-prevention assembly required to be installed by the customer under Paragraph 1 of this tariff shall comply with the requirements set forth in A.A.C. R18-4-215.D and E.
- 3. Subject to the provisions of A.A.C. R14-2-407 and 410, and in accordance with Paragraphs 1 and 7 of this tariff, the Company may terminate service or may deny service to a customer who fails to install a backflow-prevention assembly as required by this tariff
- 4. The Company shall give any existing customer who is required to install a backflow-prevention assembly written notice of said requirement. If A.A.C. R14-2-410.B.1.a. is **not** applicable, the customer shall be given thirty (30) days from the time such written notice is received in which to comply with this notice. If the customer can show good cause as to why he cannot install the backflow-prevention assembly within thirty (30) days, the Company or Commission Staff may suspend this requirement for a reasonable period of time.

Issued:

Effective:

- 5. Testing shall be in conformance with the requirements of A.A.C. R1 8-4- 215.F. The Company may require the customer to pay to have the backflow-prevention assembly tested as long as the Company does not require an unreasonable number of tests.
- 6. The customer shall provide the Company with records of installation and testing. For each backflow-prevention assembly, these records shall include:
 - a. assembly identification number and description;
 - b. location
 - c. date(s) of test(s);
 - d. description of repairs and recommendations for repairs made by tester; and
 - e. the tester's name and certificate number.
- 7. In the event the backflow-prevention assembly does not function properly or fails any test, and an obvious hazard as contemplated under A.A.C. R14-2-410.B.1.a. exists, the Company may terminate service immediately and without notice. The backflow-prevention assembly shall be repaired or replaced by the customer and retested.
- 8. In the event the backflow-prevention assembly does not function properly or fails any test, or in the event that a customer fails to comply with the testing requirement, and A.A.C. R14-2-410.B.1.a. is **not** applicable, the backflow-prevention assembly shall be repaired or replaced within fourteen (14) days of the initial discovery of the deficiency in the assembly or its function. Failure to remedy the deficiency or dysfunction of the assembly, or failure to retest, shall be grounds for termination of water service in accordance with A.A.C. R14-2-410.

Issued:

Effective: